



800.803.9256 / 414.461.8200
midwest@swgr.com
www.swgr.com

ARC FLASH HAZARD PROGRAM

(Per NFPA 70E - OSHA)

- Engineering & Field Services
- PC - PPE Guide & Risk Levels
- Systems Arc Flash Hazard Analysis
- Labeling Policy & Program
- Safety Equipment Testing



- Hands-on Safety Training
(OSHA 29 910.331-335)
- PC - PPE Guide for Electricians
- Incident Energy Levels
- Hazard Risk Levels
- Safety Equipment Testing

COMPLETE PC & PPE and SAFETY EQUIPMENT SUPPLIES